

Mbox 2 Firmware Updater v1.43 for Mac OS X and Windows XP

December 16, 2006

The following issue is fixed with Mbox 2 Firmware Updater v1.43 for Mac OS X and Windows XP:

Fixed: Certain DAT Decks Lock To The Wrong Sample Rate When Recording From Mbox 2 (Item #83265)

- When attempting a 48kHz sample rate DAT recording via the S/PDIF input, some DAT machines would either show a clock error or lock at a 44.1kHz rate, resulting in a DAT recording that would later play at the wrong speed.

Firmware Update Instructions

To update your Mbox 2 firmware from a PowerPC or Intel-based Mac:

- 1) Quit all applications and connect your Mbox 2 to your computer.
- 2) Download the correct Mbox 2 Firmware Updater v1.43 for PowerPC or Intel-based Macs to your desktop, and open the disk image.
- 3) Launch the Firmware Updater and follow the onscreen instructions.

To update your Mbox 2 firmware from a Windows PC:

- 1) Quit all applications and disconnect your Mbox 2 from your computer
- 2) Download the Mbox 2 Firmware Updater v1.43 for Windows XP to your desktop
- 3) Launch the Firmware Updater, connect your Mbox 2, and click "Update Firmware".

Compatibility

- It is only necessary to update your Mbox 2 firmware using any of these firmware updaters for either Mac OS X or Windows XP. Once your Mbox 2 Firmware has been updated, it will be compatible on both Mac OS X and Windows XP.
- Mbox 2 with firmware v1.43 is backwards compatible with any version of Pro Tools LE for Mac OS X and Windows XP that supports the Mbox 2 (Pro Tools LE 6.8.1 and higher)